

United States Steel Corporation Clairton Works 400 State Street Clairion, PA 15025

January 17, 2014

AN 29 20% JAN 29 20% JAN 29 20%

Ms. Gail Eddings Allegheny County Health Department Department of Air Quality 301 Thirty-Winth Street Pittsburgh, PA 15201

Subject: USS Reference Number: 14-0019

ACHD Reference Number: 16719

#2 Control Room USS Clairton Works

Dear Gail Eddings,

The attached form confirms our verbal report of the subject incident and satisfies the requirements of paragraph IV.8 of the Title V operating permit #0052 as issued on March 27th 2012.

I certify that based on the information and belief formed after reasonable inquiry, the statements and information in this document are true, accurate, and complete. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

ínomas E. Schumacher

Plant Manager Clairton Works

CC: James W. Hagedorn (USEPA)

## NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 14-0019 ACHD Reference Number: 16719
- 2. Date & Time of Breakdown: Date: 01/16/14 Time: 1030 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: #2 Control Room
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: Repairs to an expansion joint in the sub-sub gas line at the #2 Control Room necessitated the shut down the Light Oil Regenerators. As a result, there was a reduced level of coke oven gas processing at the #2 Control Room.
- 8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)
    Elevated Benzene in the downriver gas line systems, causing increased VOC at point of combustion.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). VOC could be an eye, nose, and throat irritant.
  - C. Amount of each type emitted (or likely to be emitted).
    Moderate
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).
  The repairs are underway.
- 10. Facility back in operation Date: Time: hours

Reviewed	by (i less) m. Dave	~ Ø	nare i / / / /	4
	Coleen M. Davis		,	***************************************
	Senior Environmental	Control Engin	eer Phone:	412-233-1015